

**Bronco Utah Operations LLC**

PO Box 527  
Emery Utah, 84522  
435-286-2447

November 6, 2018

Mr. Daron Haddock  
Utah Division of Oil, Gas and Mining  
Coal Program  
1594 West North Temple, Suite 1210  
Salt Lake City, UT 84114-5801

**RE: Bronco Utah Operations LLC  
Emery Deep Mine Permit C/015/0015  
Midterm Permit Review Deficiency Response Task ID #5670**


Dear Mr. Haddock:

Per your email request dated Monday November 5, 2018 please consider this an extension request for submittal of the above mentioned deficiency responses until December 31, 2018. As you are aware, the new topography is not available to complete the as-built drawings, revise drainage boundaries, and re-calculate the bond. We completed a rough estimate of material volumes and draft bond calculations and the current bond is adequate.

As per your request relative to a meeting to discuss bond calculations, I think it is premature at this time, as we would like to get accurate boxcut volumes prior to initiating those discussions.

If you have any questions concerning this request, please contact Kit Pappas at 435-286-2027.

Sincerely,

A handwritten signature in black ink, appearing to read "Kit Pappas", is written over a light gray rectangular background.

Kit Pappas  
Environmental Manager